

## QUALITY ALERTS - Section 17

The purpose of the Quality Alert tags is to identify parts that have a distinct characteristic to be brought to the attention of downstream customers.

The Quality Alert tag is to be Xeroxed on “**orange**” colored 8 ½” x 11” paper for visible identification. You may also use the [Quality Alert](#) form from the form file.

Mark the containers on at least two sides with the Quality Alert.

An example of use for the Quality Alert tag is for parts having a Deviation.

## PPAP ALERTS – Section 18

The purpose of the PPAP Alert tag is to identify parts that are “PPAP Sample Submission Parts.”

The PPAP Alert tag is to be Xeroxed on “**light blue**” colored 8 ½” x 11” paper for visible identification. You may also use the [PPAP Alert](#) form from the form file.

Mark the containers on at least two sides with the PPAP Alert.