

QUALITY ALERTS - Section 17

The purpose of the Quality Alert tags is to identify parts that have a distinct characteristic to be brought to the attention of downstream customers.

The Quality Alert tag is to be Xeroxed on “**orange**” colored 8 ½” x 11” paper for visible identification. You may also use the Quality Alert form from the form file.

Mark the containers on at least two sides with the Quality Alert.

An example of use for the Quality Alert tag is for parts having a Deviation.

PPAP ALERTS – Section 18

The purpose of the PPAP Alert tag is to identify parts that are “PPAP Sample Submission Parts.”

The PPAP Alert tag is to be Xeroxed on “**light blue**” colored 8 ½” x 11” paper for visible identification. You may also use the PPAP Alert form from the form file.

Mark the containers on at least two sides with the PPAP Alert.